

Follow-up from 1/11/10 PVI workgroup call

Adam Klinger, Bhooma Sundar, blavne, Bob

Pallarino, Cindy Paul, Roger Claff, george.devaull, Janice Pearson,

janice.wiegers, Jim Weaver, Jeff' 'Kuhn, John

Menatti, Joan Coyle, JohnT Wilson, Julius Matthew Young to: Shapiro, LARSEN Henning, Truesdale,

Robert S., Robin Davis, Reuter, Stephen, NMENV, Steven Linder, Thomas McHugh, todd.blessing, todd.ririe, Hers, Ian, Lowry.

Michael I.

Cc: Tamiko Cunningham

01/12/2010 07:37 AM

Thanks for participating in yesterdays call. It was a good dry run of the webinar.

Attached are the agendas for the February SLC workgroup meeting, PVI workshop webinar, and current PVI discussion outline. Please provide me with any comments you have concerning the agendas by Wednesday January 13. We will then post the agenda and extend the invites for the Webinar.







OUST Petroleum Vapor Intrusion Workshop 1_12_10.doc SLC agenda.doc PVI Guidance Discussion Outline 12_7_09.doc

As we discussed during yesterday's call, please share your potential case studies with me and RTI, ASAP, and we will select the most appropriate case studies over the next week.

Also, please provide your suggestions for issues that should be covered in the interim communication document, "The difference between PVI and CVI". Suggestions are due by January 15.

A reminder to federal and state participants, please contact Tamiko Cunningham, 703-603-7173, to make your travel arrangements.

Thanks to Julius for taking care of reserving our block of rooms. You can make your hotel reservations at the Radisson Hotel Salt Lake City Airport by calling 1-800-395-7046. Please reference the block of rooms reserved for Environmental Protection Agency-Office of Underground Storage Tanks. It is my understanding that the hotel will allow us to use their shuttles to transport us to an from the library. Here is a link to the hotel website. http://www.radisson.com/saltlakecityut/epa

Matt

Matthew A. Young, P.G. **Environmental Protection Specialist** USEPA/OSWER/OUST Implementation Division 2733 S. Crystal City Dr., 4th Floor Arlington, VA 22202

Direct (703) 603-7143 Fax (703)603-0175

Mailing Address: 1200 Pennsylvania Ave, NW MC 5401P Washington, DC 20460-0001 801-364-5800 4 miles 4372666 > \$101. 7-10



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

LU-9J

Certified mail Return Receipt Requested

Metal Management Midwest, Inc. Attn: Ms. Debbie Hays 12701 South Doty Avenue Chicago, Illinois 60633

Certified Mail: 7001 0320 0006 1453 9889 Return Receipt Requested

CPI Environmental Services Attn: Mr. Michael B. Place 1123 Wheaton Oaks Court Wheaton, IL 60187

RE: PCB Remedial Action Completion Report 1509 Courtland Street, Chicago IL 60642-1215

Dear Ms. Hays and Mr. Place:

I have completed the review of the PCB Remedial Action Completion Report Submitted on November 16, 2009 for the Metal Management Midwest, Inc. property located at 1509 Courtland Street in Chicago, Illinois.

U.S.EPA approves the remedial action undertaken at Area A and Area B. The confirmatory sample results indicate that remedial action objective is met at Area A and Area B. This allows for risk-based closure of residual PCB soil concentration at the property. Please proceed with the construction of impermeable surface barrier as defined in the IEPA approved Remedial Action Plan.

While Establishing Institutional controls to limit the future use of the property, Metal Management Midwest, Inc shall record a notation on the deed to the property, that will in perpetuity notify any potential purchaser of the property that a risk-based approval for cleanup

and disposal of PCB remediation waste has been issued by the U.S.EPA, and that the property is restricted to industrial land use.

Within 60 days of obtaining the IEPA No Further Remediation (NFR) letter, the owner of the Metal Management Midwest, Inc should submit a certification that he/she has recorded the notation as specified in the above paragraph.

Please note that this approval does not relieve you from your duty to comply with all other applicable federal, state, and local requirements. If you have any questions, please contact me by e-mail at sundar.bhooma@epa.gov or by telephone at (312) 886-1660.

Sincerely,

Bhooma Sundar Project Manager

cc: Mr. Todd Hall Illinois Environnemental Protection Agency

Mr. Todd Hall Illinois Environmental Protection Agency Bureau of Land Remedial Project Management Section 1021 North Grand Avenue East Springfield, IL 62794-9276

PCB REMEDIAL ACTION COMPLETION REPORT

Metal Management Midwest, Inc. (DBA Sims Metal Management) 1509 West Cortland Street Chicago, Illinois 60622

Prepared for:

Metal Management Midwest, Inc. 12701 South Doty Avenue Chicago, IL 60633

Prepared by:

CPI Environmental Services, Inc.

1123 Wheaton Oaks Court Wheaton, IL 60187

CPI Project No.: E05-258-22-768

November 06, 2009

TABLE OF CONTENTS 1.0 INTRODUCTION......1 1.1 Project Background......1 1.2 2.0 2.1 Preparation for Field Activities......3 2.2.1 Material Removal and Characterization4 2.2.2 Excavation Confirmatory Sampling......5 DISCUSSION OF SAMPLING RESULTS7 3.0 3.1 3.2 ENGINEERING AND INSTITUTIONAL CONTROLS9 4.0 **FIGURES** Figure 1. Property Location Map Figure 2. Areas A and B Excavation Locations with PCB Sample Results **TABLES** Table 1. Summary of Remediation Waste Characterization Sample Results Table 2. Summary of Excavation Confirmatory Sample Results APPENDICES

Appendix 1, U.S. EPA Risk-Based PCB Cleanup Approval Letter

APPENDICES (Cont.)

- Appendix 2. Photographic Log
- Appendix 3. Laboratory Analytical Report for Waste Characterization Sample
- Appendix 4. Generator Waste Profile, Waste Manifest and Scale Ticket
- Appendix 5. Laboratory Analytical Report for Excavation Confirmatory Samples

Page ii

1.0 INTRODUCTION

1.1 Project Background

CPI Environmental Services, Inc. (CPI) has prepared this PCB Remedial Action Completion Report on behalf of Metal Management Midwest, Inc. (MMMI) for the MMMI property referred to as the Cometco facility, located at 1509 West Cortland Street in Chicago, Illinois (Subject Property), as shown on Figure 1. The Property currently operates as a scrap metal recycling facility.

MMMI enrolled the Property for voluntary site cleanup in the Illinois Environmental Protection Agency's (IEPA's) Site Remediation Program (SRP) as promulgated at 35 Illinois Administrative Code (IAC) 740 Site Remediation Program. The Property was accepted into the SRP on June 28, 2001. As part of comprehensive investigation activities conducted in accordance with the SRP, sampling revealed the presence of property-wide polychlorinated biphenyls (PCBs) impact to soil. The soil impact was defined and limited to historic fill material at the Property. Due to the concentration of PCBs detected in fill material, IEPA requested that the PCBs be managed in accordance with 40 CFR 761 through the United States EPA (U.S. EPA).

As a result, CPI prepared a Baseline Human Health Risk Assessment Report (BHHRA) in February 2007, which presented to U.S. EPA a risk-based remediation option for the PCB impacted fill material pursuant to 40 CFR §761.61(c). In May 2009, U.S. EPA approved CPI risk-based closure option under the condition that fill material exhibiting PCB concentrations in excess of 50 mg/kg at two locations TP-302 and TP-310 (defined as Area A and Area B, respectively, in the BHHRA) be removed from the Property and managed as PCB remediation waste. A copy of U.S. EPA's approval letter of CPI's risk-based cleanup approach is provided in Appendix 1.

Metal Management Midwest, Inc.

CPI Environmental Services, Inc. Project No.: E05-258-22-768

Page 1

PCB REMEDIAL ACTION COMPLETION REPORT Metal Management Midwest, Inc. 1509 West Cortland Street, Chicago, Illinois

1.2 Report Objectives

This RACR focuses on the remediation of portions of the Property referred to as Area A and Area B, where prior investigation identified the presence of PCBs in excess of 50 mg/kg in soil (Figure 2). As part of the remedial action reported herein, soil within Areas A and B have been remediated and post-excavation soil sample results demonstrate that the remedial actions performed meet required conditions established by U.S. EPA for risk-based closure following construction of an engineered barrier and establishment of industrial land use restriction in accordance with 35 IAC 742.1100 and 742.1000.

Therefore, to proceed with installation of an engineered barrier and to establish land use controls at the Property based on the results of remedial action presented in this report CPI, on behalf of MMMI, requests that U.S. EPA:

- 1. Review and approve the remedial actions undertaken at Area A and Area B.
- Confirm that the results of the actions performed and reported herein demonstrate that the
 remediation objectives have been met in Area A and Area B to allow for risk-based
 closure of remaining PCB soil concentrations at the Property.

This RACR includes a narrative of field activities and remedial actions; discussion of special conditions including engineered barriers and institutional controls; results of Areas A and B post-excavation sampling; remediation waste characterization and disposal; and CPI's conclusions pertaining to the remediation of Areas A and B.

Metal Management Midwest, Inc. CPI Environmental Services, Inc. Project No.: E05-258-22-768

2.0 FIELD ACTIVITIES AND REMEDIAL ACTIONS

The following general field activities were performed during the remediation of Areas A and B:

- 1. Locating Areas A and B for soil excavation;
- 2. Excavating, characterizing and transporting PCB containing fill material for off-site disposal at a permitted solid waste facility;
- 3. Post-excavation soil sampling and laboratory analysis to confirm compliance with U.S. EPA approved risk-based cleanup approach; and
- 4. Backfilling of excavation areas.

2.1 Preparation for Field Activities

Prior to commencing the field activities, the following tasks were performed:

- Areas A and B as presented in Figure 2 were located by survey methods based on measurements collected during prior field sampling activities;
- Facility personnel were interviewed and site drawings were reviewed to identify potential excavation hindrances resulting from ongoing operations;
- Appropriate areas for staging of excavated soil were identified by coordinating with Property operations personnel; and
- Location of Property underground utilities were identified in areas of excavation.

2.2 Remedial Activities

The following remedial activities were performed during soil excavation at Areas A and B:

Metal Management Midwest, Inc. Page 3

CPI Environmental Services, Inc. Project No.: E05-258-22-768

- Removing fill material consisting of silty clay with varying amounts of small metallic pieces, wood, asphalt millings and cinders to a depth of approximately four feet below ground surface at Areas A and B;
- Loading of excavated material into a 20-ton capacity, plastic-lined roll-off container;
- Characterizing excavated material placed in roll-off container for proper disposal in a permitted solid waste facility;
- Collecting post-excavation confirmation soil samples from the excavation sidewalls and floor in general accordance with 40 CFR §761.280 requirements;
- Comparing the laboratory analytical results of soil samples to determine that established risk-based cleanup criteria are achievable; and
- Backfilling excavation areas

Photographs of field activities, including a photographic log, are contained in Appendix 2.

2.2.1 Material Removal and Characterization

Fill material within the delineated boundaries of Areas A and B, which measured approximately four feet in a north to south direction by three feet in an east to west direction at Area A and four feet in an east to west direction by three feet in a north to south direction at Area B, was removed to a depth of approximately four feet below grade on August 19, 2009. A rubber-tired combination backhoe was utilized by Cabeno Environmental Field Services, Inc. personnel to excavate the material. The excavated material was place directly into a 20-ton capacity, plastic-lined roll-off container. Depths of excavations were terminated upon encountering native silty clay soil where prior investigation sample results did not identify the presence of PCB concentrations.

Once excavation activities were completed, a representative sample of the remediation waste, which was placed into the roll-off container, was collected by CPI personnel for characterizing the material for proper disposal. Following collection of that sample, a tarp was placed over the

top of the container and the container was stored on-site until permit arrangements for off-site disposal were made.

In order to obtain a representative sample of the excavated material, three locations (front, middle and back) within roll-off container were selected. At each location an approximate eightounce sample aliquot was obtained from the top, middle and bottom portion of the soil. A soil hand auger was used to obtain sample aliquots from the middle and bottom portions of the container. Following collection, each of the three sample aliquots obtained from the front, middle and back portions of the roll-off container were placed into a large stainless steel bowl. Material in the bowl was then thoroughly mixed and homogenized by hand. A portion of the homogenized soil mixture was the transferred from the bowl by hand and placed into a laboratory-supplied 32-ounce glass jar. The jar was then labeled and placed into an iced cooler for delivery to the laboratory for waste characterization.

Waste characterization analytical parameters were selected based on disposal facility permit requirements. The sample was analyzed for Toxicity Characteristic Leaching Procedure (TCLP) volatile, semi-volatile organic compounds and RCRA metals, PCBs, reactive cyanide, reactive sulfide, ignitability, pH and paint filter. Results of the waste characterization sample are presented on Table 1 and discussed in Section 3.0

2.2.2 Excavation Confirmatory Sampling

To verify lateral and vertical limits of soil remediation was successful, CPI personnel collected samples from the sidewalls and bottom of each excavation area. The sampling was performed in general accordance with 40 CFR §761.280. Sidewall samples were collected from the entire thickness of fill material present at each excavation area. The four sidewall samples collected were then composited into one sample at each excavation area and analyzed for PCBs. In addition, a soil sample from the native silty clay at the bottom of each excavation also was collected and analyzed for PCBs. Those samples were collected at the center of the excavation

Metal Management Midwest, Inc.

CPI Environmental Services, Inc. Project No.: E05-258-22-768

areas from within the first six-inch depth interval beneath the bottom surface. Upon collection, each sample jar was labeled and placed in an iced cooler for delivery to the laboratory.

2.2.3 Excavation Backfilling

Following receipt of analytical results from confirmatory sampling indicating PCB concentrations were acceptable, the excavations were backfilled with clean material by MMMI personnel and equipment.

3.0 DISCUSSION OF SAMPLING RESULTS

3.1 Waste Characterization Sample Results

Results of the waste characterization sample (Comp-1) collected from excavated material did not contain TCLP volatile or semi-volatile organic compounds, reactive cyanide, or reactive sulfide in excess of the laboratory detection limits. Low concentrations of TCLP RCRA metals were identified, except for silver. A total PCB concentration of 0.551 mg/kg was detected in the sample.

Table 1 presents a summary of the remediation waste characterization sample (Comp-1) results. The laboratory report and chain-of-custody documentation form are included in Appendix 3.

Based on the waste characterization results and in accordance with U.S. EPA risk-based cleanup approval condition A.1.a, CPI made arrangements to permit the remediation waste for disposal in a licensed Subtitle D facility as an Illinois special waste. On October 8, 2009 the roll-off container was transported under manifest by SET Environmental, Inc., a licensed Illinois special waste transporter, to Waste Management's Countryside Recycling and Disposal Facility located in Grayslake, Illinois for disposal. A total of 10.7 tons of soil was disposed.

Copies of the generator waste profile information for disposal acceptance, waste manifest and scale ticket are included in Appendix 4.

3.2 Confirmatory Excavation Sample Results

Results of samples collected from the sidewalls (designated as TP-302 Comp and TP-310 Comp) and bottom (designated as TP-302B and TP-310B) are summarized on Table 2. The bottom samples collected from native silty clay soil at both excavation areas did not contain PCB

Metal Management Midwest, Inc.

Page 7

PCB REMEDIAL ACTION COMPLETION REPORT
Metal Management Midwest, Inc.
1509 West Cortland Street, Chicago, Illinois

concentrations in excess of the laboratory detection limits of 0.041 mg/kg for TP-302B or 0.046 mg/kg for TP-310B. The composite sidewall samples TP-302 Comp and TP-310 Comp of fill material at each excavation area were found to contain low concentrations (0.299 mg/kg and 0.564 mg/kg, respectively) of Aroclor 1260. The remaining Aroclors from sidewall samples

The laboratory report and chain-of-custody documentation form for excavation area samples are

were not identified in excess of the laboratory detection limit of 0.038 mg/kg.

contained in Appendix 5.

Page 8

4.0 ENGINEERING AND INSTITUTIONAL CONTROLS

Engineered controls will consist of a site-wide impermeable surface to be placed over affected areas of the Property as defined in the IEPA approved Remedial Action Plan (RAP), including The nature of the barrier to be installed, the operation and maintenance plan, Areas A and B. and construction worker protection will be determined in accordance with the RAP Section F following approval form U.S. EPA that the PCB impacted fill material at Areas A and B have successfully been remediated to allow for risk-based closure approval.

Institutional controls will be established to limit the future use of the Property to industrial/commercial. Those controls will be established through an IEPA No Further Remediation (NFR) letter following construction of the engineered barrier. As required, the NFR will be recorded with the County Clerk and become a permanent record attached to the chain of title to the Property.

Metal Management Midwest, Inc.


CPI Environmental Services, Inc. Project No.: E05-258-22-768

PCB REMEDIAL ACTION COMPLETION REPORT Metal Management Midwest, Inc. 1509 West Cortland Street, Chicago, Illinois

FIGURES

Figure 1. Property Location Map

Figure 2. Areas A and B Excavation Locations with PCB Sample Results



CPI Environmental Services, Inc. 1123 Wheaton Oaks Ct. Wheaton, IL 60187 (630) 407-0800


CPI Project No.:

E05-258-22-768

FIGURE 1:

SUBJECT PROPERTY LOCATION MAP

SOURCE: National Geographic USGS Seamless Topographic Map



CPI Environmental Services, Inc.

1123 WHEATON DAKS COURT
WHEATON, ILLINOIS 60187

NOTE

BASE MAP BASED ON CHICAGO GUARANTEE SURVEY COMPANY TOPOGRAPHIC SURVEY MAP DATED JULY 1, 1991

KEY MAP

0.568/0.998 - ANALYTICAL RESULTS OBTAINED FROM 2
SAMPLES WITHIN FILL MATERIAL COLLECTED
FROM DIFFERENT DEPTHS; FIRST NUMBER
REPRESENTS SHALLOWER DEPTH SAMPLE;
SEE ANALYTICAL TABLES FOR CORRESPONDING
DEPTHS

ND - NOT DETECTED

(C) - SILTY CLAY RESULTS TOTAL PCB

1.00 - DETECTED CONCENTRATION (MG/KG)

- STORMWATER RETENTION POND

- PCB EXPOSURE AREA

TP-118 - TEST PIT SAMPLE LOCATION (8/31/2000)

B-207 • BOREHOLE SAMPLE LOCATION (10/11/2000)

h.TP-312 • TEST PIT SAMPLE LOCATION (10/17/2000)

O 8-341 - BOREHOLE SAMPLE LOCATION (10/24/2000)

S3 - E & E SAMPLE LOCATION (1/20/1999)

- BOREHOLE SAMPLE LOCATION (11/21/2006) (SEE TABLE 1 FOR RESULTS)

- GROUNDWATER MONITORING WELL

- CONCRETE PAD

- CONCILIE I

- CROSS SECTION LINE LOCATIONS

0	80 FEET	
CREATED 01/12/2007	DRAWN DPC	APVD SAS
REVISIONS		
LEVELS		
LEVELS FILE NAME		

COMETCO CORPORATION
1509 WEST CORTLAND STREET
CHICAGO, ILLINOIS

TITLE

Figure 2
Areas A and B Locations
with PCB Sample Results

TABLES

- Table 1. Summary of Remediation Waste Characterization Sample Results
- Table 2. Summary of Excavation Confirmatory Sample Results

TABLE 1 SUMMARY OF WASTE CHARACTERIZATION SAMPLE RESULTS METAL MANAGEMENT MIDWEST, INC. COMETCO FACILITY

	Sample I.D.
Parameters	COMP-1
TCLP Volatile Organic Compounds	
Benzene	<0.125 mg/l
2-Butanone	<0.125 mg/L <0.125 mg/L
Carbon tetrachloride	
	<0.125 mg/L
Chlorobenzene	<0.125 mg/L
Chloroform	<0.125 mg/L
1,4-Dichlorobenzene	<0.125 mg/L
1,2-Dichloroethane	<0.125 mg/L
1,1-Dichlorethane	<0.125 mg/L
Tetrachloroethene	<0.125 mg/L
Trichloroethene	<0.125 mg/L
Vinyl chloride	<0.100 mg/L
TCLP Semi Volatile Organic Compou	nds
1,4-Dichlorobenzene	<0.0100 mg/L
2,4-Dinitrotoluene	<0.0100 mg/L
Hexachlorobenzene	<0.0100 mg/L
Hexachlorobutadiene	<0.0100 mg/L
Hexachloroethane	<0.0100 mg/L
2-Methylphenol	<0.0100 mg/L
3 & 4-Methylphenol	<0.0200 mg/L
Nitrobenzene	<0.0100 mg/L
Pentachlorophenol	<0.0500 mg/L
Pyridine	<0.0500 mg/L
2,4,5-Trichlorophenol	<0.0100 mg/L
2,4,6-Trichlorophenol	<0.0100 mg/L
Polychlorinated Biphenyls	
Aroclor 1016	<0.0347 mg/kg
Aroclor 1221	<0.0347 mg/kg
Aroclor 1232	<0.0347 mg/kg
Aroclor 1232	<0.0347 mg/kg
Aroclor 1242	<0.0347 mg/kg
Aroclor 1248	<0.0347 mg/kg
Aroclor 1245	<0.0347 mg/kg
Aroclor 1260	0.551mg/kg
TCLP RCRA Metals	
	0.00655
Arsenic	0.00655 mg/L
Barium	0.636 mg/L
Cadmium	0.0184 mg/L
Chromium	0.0269 mg/L
Lead	0.166 mg/L
Mercury	0.000353 mg/L
Selenium	0.00808 mg/L
Silver	< 0.005 mg/L
Conventional Chemistry Parameters	
Reactive Cyanide	<1.07 mg/kg
Ignitability	>195 °F
Paint Filter	Pass
рН	7.10 S.U.
Reactive Sulfide	<9.3 mg/kg

TABLE 2 SUMMARY OF EXCAVATION CONFIRMATORY SAMPLE RESULTS METAL MANAGEMENT MIDWEST, INC. COMETCO FACILITY

	Excavation Location			
	AREA A		AREA B	
Parameters	TP-302B	TP-302 Comp	TP-310B	TP-310 Comp
Parameters Polychlorinated Biphenyls (PCBs) [mg] [kg] Aroclor 1016				
Aroclor 1016	<0.046	<0.038	<0.046	<0.038
Aroclor 1221	<0.046	<0.038	<0.046	<0.038
Aroclor 1232	< 0.046	<0.038	<0.046	<0.038
Aroclor 1232	<0.046	<0.038	< 0.046	<0.038
Aroclor 1242	< 0.046	<0.038	< 0.046	<0.038
Aroclor 1248	< 0.046	<0.038	<0.046	<0.038
Aroclor 1245	<0.046	<0.038	<0.046	<0.038
Aroclor 1260	< 0.046	0.299	< 0.046	0.564
Total PCBs	<0.046	0.299	< 0.046	0.564

APPENDICES

- Appendix 1. U.S. EPA Risk-Based PCB Cleanup Approval Letter
- Appendix 2. Photographic Log
- Appendix 3. Laboratory Analytical Report for Waste Characterization Sample
- Appendix 4. Generator Waste Profile, Waste Manifest and Scale Ticket
- Appendix 5. Laboratory Analytical Report for Excavation Confirmatory Samples

APPENDICES

Appendix 1. U.S. EPA Risk-Based PCB Cleanup Approval Letter



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

MAY 0 7 2009

REPLY TO THE ATTENTION OF

L-8J

Certified Mail: Return Receipt Requested

Metal Management Midwest, Inc. Attn: Ms. Debbie Hays 12701 South Doty Avenue Chicago, Illinois 60633

Certified Mail: Return Receipt Requested

CPI Environmental Services Attn: Mr. Michael B. Place 799 Roosevelt Road Building 6, Suite 110 Glen Ellyn, Illinois 60137

> RE: Risk-Based PCB Cleanup Approval 1509 Courtland Street, Chicago IL 60642-1215

Dear Ms. Hays and Mr. Place:

We have completed our review of your February 7, 2007 application (entitled Baseline Human Health Risk Assessment) for approval of a risk-based cleanup under 40 CFR 761.61(c) for the Metal Management Midwest, Inc. property located at 1509 Courtland Street in Chicago, Illinois. In addition to the information in your application, Mr. Place has also agreed that Metal Management Midwest, Inc. will remove the soil represented by samples TP 302 and TP 310 and dispose of it off-site in an appropriate landfill.

There are several other locations at this facility where the PCB concentrations in soils exceed the self-implementing cleanup levels found at 40 CFR 761.61(a)(4). Based on the information provided in your application, we have determined that the existing PCB soil contamination represented by those other samples does not pose an unreasonable risk of injury to human health or the environment, as long as the land use of the property is restricted.

We also understand that there are other chemical contaminants in the soils at this facility, and that you are working with the Illinois EPA to clean up those contaminants under a Remedial Action Plan (RAP). We expect that this will result in engineered barriers constructed and maintained over the entire contaminated area of the property. The requirements for construction, inspection, and maintenance of the engineered barrier will be established through the RAP approval process.

Accordingly, your application is hereby approved, subject to the conditions contained in the enclosure to this letter.

Please note that this approval does not relieve you from your duty to comply with all other applicable federal, state, and local requirements. If you have any questions, please contact Bhooma Sundar by e-mail at sundar.bhooma@epa.gov or by telephone at (312) 886-1660.

Sincerely,

Margaret M. Guerriero

Director

Land and Chemicals Division

Enclosure

cc: Mr. Todd Hall

Illinois Environnemental Protection Agency

Approval Conditions

A. Remedial Action

- 1. Metal Management Midwest Inc. shall remove accessible PCB remediation waste at locations TP 302 and TP 310 (defined as "Area A"and "Area B" respectively in the BHHRA report).
 - a. All remediation waste containing concentrations of PCBs less than 50 ppm shall be disposed of in accordance with 40 C.F.R.761.61 (a)(5)(v)(A), as required by 40 CFR 761.61(a)(5)(i)(B)(2)(ii).
 - b. All remediation waste containing concentration of PCBs greater than or equal to 50 ppm shall be disposed of in accordance with 40 C.F.R. 761.61(a)(5)(i)(B)(iii) in that it shall be disposed of in a hazardous waste landfill permitted by the U.S. EPA under section 3004 of RCRA, 42 U.S.C.6924, or by a state authorized under section 3006 of RCRA, 42 U.S.C.6926, or at a PCB disposal facility approved under 40 C.F.R. Part 761.

B. Land Use Restriction and Notice

- 1. The property must be restricted to industrial land use.
- 2. Within 60 days of completion of the cleanup activity, Metal Management Midwest, Inc. shall record, in accordance with State law, a notation on the deed to the property, or on some other instrument which is normally examined during a title search, that will in perpetuity notify any potential purchaser of the property that a risk-based approval for cleanup and disposal of PCB remediation waste has been issued by the U.S. EPA, and that the property is restricted to industrial land use.

C. Reporting

- 1. With in 60 days of competing the remediation under this approval, Metal Management Midwest, Inc. must submit to EPA, Region 5 a remedial action completion report that includes a summary of the sampling analytical results, a description of the final cap, a summary of the off-site disposal activities, and a certification that the cleanup has been conducted and completed in accordance with this approval.
- 2. Reports or information required by this approval must be submitted to:

U.S. EPA, Region 5 Attn: Bhooma Sundar Remediation and Reuse Branch 77 W. Jackson Blvd., LU-9J Chicago, IL 60604

D. Change of Ownership

1. Metal Management Midwest, Inc. must notify U.S. EPA thirty days prior to any change in ownership of the property. Such notice must include the name, address and telephone number of the new owner, and the name of the new owner's contact person for this matter. Metals Management Midwest, Inc. must also submit a letter, signed by the potential purchaser, stating whether it intends to maintain the industrial land use, or whether it intends to remove and dispose of additional PCB-contaminated soils off-site instead.

Appendix 2. Photographic Log

Photographic Log



Photo #1 – Location of Area A (TP-302) prior to excavation.



Photo #2 - Location of Area B (TP-310) prior to excavation.

Photographic Log (Continued)



Photo #3 – Lined roll-off box adjacent to excavation Area A.



Photo #4 - Commencement of Area A (TP-302) excavation.

Photographic Log (Continued)



Photo #5 - Extent of Area A (TP-302) excavation.



Photo #6 - Commencement of Area B (TP-310) excavation.

Photographic Log (Continued)



Photo #7 – Extent of Area B (TP-310) excavation.



Photo #8 - View of covered roll-off box staged on-site pending waste characterization results.

Appendix 3.	Laboratory	Analytical Report for	Waste Characterization
		Sample	



Tuesday, September 22, 2009

Mr. Frank Santella

CPI Environmental Services, Inc. 1123 Wheaton Oaks Court Wheaton, IL 60187

TEL: (630) 407-0800 FAX: (630) 407-0799

RE: Cometco / Chicago, IL

PAS WO:

09H0388

Prairie Analytical Systems, Inc. received 1 sample(s) on 8/20/2009 for the analyses presented in the following report.

All applicable quality control procedures met method specific acceptance criteria unless otherwise noted.

This report shall not be reproduced, except in full, without the prior written consent of Prairie Analytical Systems, Inc.

If you have any questions, please feel free to contact me at (217) 753-1148.

Respectfully submitted,

Kristen A. Potter

Project Manager

Certifications:

NELAP/NELAC - # 100323

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

Client Sample ID: Comp 1

Lab ID: 09H0388-01

Collection Date:

8/19/09 12:15

Matrix: Solid

Result U U U U U U U U U U U U U U U U U U	0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.126 0.129 0.129 0.129 0.129 0.129 0.129 0.129 0.129 0.129 0.129 0.129 0.129 0.129	Qual Units mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L 67-86-8/-8/-8/-8/-8/-8/-8/-8/-8/-8/-8/-8/-8/-		8/27/09 8:56 8/27/09 8:56	8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17	SW 8260B SW 8260B	BDP BDP BDP BDP BDP BDP BDP BDP BDP BDP
U U U U U U U U U U U U U U U U U	0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.100 103 %	mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L	5 5 5 5 5 5 5 5 5 5	8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56	8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17	SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B	BDP BDP BDP BDP BDP BDP BDP
UUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUU	0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.100 103 %	mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L	5 5 5 5 5 5 5 5 5 5	8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56	8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17	SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B	BDP BDP BDP BDP BDP BDP BDP
UUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUUU	0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.100 103 %	mg/L mg/L mg/L mg/L mg/L mg/L mg/L mg/L	5 5 5 5 5 5 5 5 5	8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56	8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17	SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B	BDP BDP BDP BDP BDP BDP BDP
U U U U U U U	0.125 0.125 0.125 0.125 0.125 0.125 0.125 0.100 103 % 98 %	mg/L mg/L mg/L mg/L mg/L mg/L mg/L 67- 86-	5 5 5 5 5 5 5 5	8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56	8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17	SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B	BDP BDP BDP BDP BDP BDP
U U U U U U	0.125 0.125 0.125 0.125 0.125 0.125 0.100 103 % 98 %	mg/L mg/L mg/L mg/L mg/L mg/L mg/L 67- 86-	5 5 5 5 5 5 5	8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56	8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17	SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B	BDP BDP BDP BDP BDP
U U U U U	0.125 0.125 0.125 0.125 0.125 0.100 103 % 98 %	mg/L mg/L mg/L mg/L mg/L mg/L 67- 86-	5 5 5 5 5 5	8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56	8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17	SW 8260B SW 8260B SW 8260B SW 8260B SW 8260B	BDP BDP BDP BDP
U U U U U	0.125 0.125 0.125 0.125 0.100 103 % 98 %	mg/L mg/L mg/L mg/L mg/L 67- 86-	5 5 5 5 5	8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56	8/27/09 10:17 8/27/09 10:17 8/27/09 10:17 8/27/09 10:17	SW 8260B SW 8260B SW 8260B SW 8260B	BDP BDP BDP
U U U U	0.125 0.125 0.125 0.100 103 % 98 %	mg/L mg/L mg/L mg/L 67- 86-	5 5 5 5	8/27/09 8:56 8/27/09 8:56 8/27/09 8:56 8/27/09 8:56	8/27/09 10:17 8/27/09 10:17 8/27/09 10:17	SW 8260B SW 8260B SW 8260B	BDP BDP
U U U	0.125 0.125 0.100 103 % 98 %	mg/L mg/L mg/L 67- 86-	5 5 5	8/27/09 8:56 8/27/09 8:56 8/27/09 8:56	8/27/09 10:17 8/27/09 10:17	SW 8260B SW 8260B	BDP
U U mpounds by GC-MS	0.125 0.100 103 % 98 %	mg/L mg/L 67- 86-	5 5 133	8/27/09 8:56 8/27/09 8:56	8/27/09 10:17	SW 8260B	
U Impounds by GC-MS	0.100 103 % 98 %	mg/L 67- 86-	5 133	8/27/09 8:56			BDP
mpounds by GC-MS	103 % 98 %	67-, 86-,	133		8/27/09 10:17		
• •	98 %	86-			0.27.07 (0.17	SW 8260B	BDP
• •			125	8/27/09 8:56	8/27/09 10:17	SW 8260B	BDP
• •	96 %	81-	122	8/27/09 8:56	8/27/09 10:17	SW 8260B	BDP
• •			116	8/27/09 8:56	8/27/09 10:17	SW 8260B	BDP
• •		·					
	0.0100	mg/L	1	8/24/09 10:45	8/25/09 17:25	SW 8270C	СЈМ
Ū	0.0100	mg/L	1	8/24/09 10:45	8/25/09 17:25	SW 8270C	CJM
Ü	0.0100	mg/L	1	8/24/09 10:45	8/25/09 17:25	SW 8270C	СЛМ
		•					СЛМ
		<u> </u>					СЛМ
		-					CJM
		=					CJM
•		-					CJM
		-					СЛМ
		_					CJM
		_					CJM
		*					CJM
· ·		-					CJM
							CJM
							CJM
							CJM
	118 %			8/24/09 10:45 8/24/09 10:45	8/25/09 17:25 8/25/09 17:25	SW 8270C SW 8270C	CJM CJM
a non							
	0.021			0/04/05 3 3 7 5	0.000.000	0111 0	
							CJM
							CJM
							CJM
	0.0347			8/24/09 16:22	8/25/09 17:35	SW 8082	СЈМ
				8/24/09 16:22			СЛМ
				8/24/09 16:22	8/25/09 17:35	SW 8082	CJM
0.551		= -		8/24/09 16:22	8/25/09 17:35	SW 8082	CJM
	78 %	60-	140	8/24/09 16:22	8/25/09 17:35	SW 8082	CJM
	85 %	60-	140	8/24/09 16:22	8/25/09 17:35	SW 8082	СЈМ
0.00655	0.00500	mg/L	1	8/26/09 12:15	0.10.00.00.00.00.00	0741 4050 I	лс
		U 0.0100 U 0.0100 U 0.0200 U 0.0100 U 0.0500 U 0.0500 U 0.0100 U 0.0100 U 0.0100 U 0.0100 U 0.0347	U 0.0100 mg/L U 0.0100 mg/L U 0.0200 mg/L U 0.0500 mg/L U 0.0500 mg/L U 0.0500 mg/L U 0.0100 mg/L U 0.0100 mg/L U 0.0100 mg/L 78 % 38-64 % 12-80 % 42-42 % 15-103 % 42-118 % 20- C-ECD U 0.0347 mg/Kg dry	U 0.0100 mg/L 1 U 0.0100 mg/L 1 U 0.0200 mg/L 1 U 0.0100 mg/L 1 U 0.0500 mg/L 1 U 0.0500 mg/L 1 U 0.0500 mg/L 1 U 0.0100 mg/L 1 U 0.0100 mg/L 1 U 0.0100 mg/L 1 U 0.0100 mg/L 1 O 0.0100 mg/L	U 0.0100 mg/L 1 8/24/09 10:45 U 0.0100 mg/L 1 8/24/09 10:45 U 0.0200 mg/L 1 8/24/09 10:45 U 0.0100 mg/L 1 8/24/09 10:45 U 0.0500 mg/L 1 8/24/09 10:45 U 0.0500 mg/L 1 8/24/09 10:45 U 0.0100 mg/L 1 8/24/09 10:45 U 0.0100 mg/L 1 8/24/09 10:45 U 0.0100 mg/L 1 8/24/09 10:45 78 % 38-149 8/24/09 10:45 64 % 12-95 8/24/09 10:45 80 % 42-156 8/24/09 10:45 42 % 15-90 8/24/09 10:45 103 % 42-137 8/24/09 10:45 118 % 20-120 8/24/09 10:45 C-ECD U 0.0347 mg/Kg dry 1 8/24/09 16:22 85 % 60-140 8/24/09 16:22 85 % 60-140 8/24/09 16:22	U 0.0100 mg/L 1 8/24/09 10:45 8/25/09 17:25 U 0.0100 mg/L 1 8/24/09 10:45 8/25/09 17:25 U 0.0200 mg/L 1 8/24/09 10:45 8/25/09 17:25 U 0.0100 mg/L 1 8/24/09 10:45 8/25/09 17:25 U 0.0500 mg/L 1 8/24/09 10:45 8/25/09 17:25 U 0.0500 mg/L 1 8/24/09 10:45 8/25/09 17:25 U 0.0100 mg/L 1 8/24/09 10:45 8/25/09 17:25 48 38-149 8/24/09 10:45 8/25/09 17:25 64 % 12-95 8/24/09 10:45 8/25/09 17:25 80 % 42-156 8/24/09 10:45 8/25/09 17:25 42 % 15-90 8/24/09 10:45 8/25/09 17:25 42 % 15-90 8/24/09 10:45 8/25/09 17:25 103 % 42-137 8/24/09 10:45 8/25/09 17:25 118 % 20-120 8/24/09 10:45 8/25/09 17:25 C-ECD U 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 U 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 U 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 U 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 U 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 U 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 U 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 U 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 U 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 U 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 0.551 0.0347 mg/Kg dry 1 8/24/09 16:22 8/25/09 17:35 85 % 60-140 8/24/09 16:22 8/25/09 17:35	U 0.0100 mg/L 1 8/24/09 10:45 8/25/09 17:25 SW 8270C U 0.0200 mg/L 1 8/24/09 10:45 8/25/09 17:25 SW 8270C U 0.0200 mg/L 1 8/24/09 10:45 8/25/09 17:25 SW 8270C U 0.0100 mg/L 1 8/24/09 10:45 8/25/09 17:25 SW 8270C U 0.0500 mg/L 1 8/24/09 10:45 8/25/09 17:25 SW 8270C U 0.0500 mg/L 1 8/24/09 10:45 8/25/09 17:25 SW 8270C U 0.0500 mg/L 1 8/24/09 10:45 8/25/09 17:25 SW 8270C U 0.0100 mg/L 1 8/24/09 10:45 8/25/09 17:25 SW 8270C U 0.0100 mg/L 1 8/24/09 10:45 8/25/09 17:25 SW 8270C U 0.0100 mg/L 1 8/24/09 10:45 8/25/09 17:25 SW 8270C Mg/L 1 8/24/09 10:45 8/25/09 17:35 SW 8082 Mg/L 1 8/24/09 10:45 8/25/09 17:35 SW 8082 Mg/L 1 8/24/09 16:22 8/25/09 17:35 SW 8

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

Client Sample ID: Comp 1

Lab 1D: 09H0388-01

Collection Date:

8/19/09 12:15

Matrix: Solid

Analyses	Result	Limit	Qual Units	DF	Date Prepared	Date Analyzed	Method	Analyst
*Barium	0.636	0.00500	mg/L	ı	8/26/09 12:15	8/27/09 2:51	SW 6020A	JTC
*Cadmium	0.0184	0.00200	mg/L	1	8/26/09 12:15	8/27/09 2:51	SW 6020A	JTC
*Chromium	0.0269	0.00200	mg/L	1	8/26/09 12:15	8/27/09 2:51	SW 6020A	JTC
*Lead	0.166	0.00500	mg/L	1	8/26/09 12:15	8/27/09 2:51	SW 6020A	JTC
*Mercury	0.000353	0.000200	mg/L	1	8/26/09 12:15	8/27/09 2:51	SW 6020A	JTC
*Selenium	0.00808	0.00500	mg/L	l	8/26/09 12:15	8/27/09 2:51	SW 6020A	JTC
*Silver	U	0.00500	mg/L	1	8/26/09 12:15	8/27/09 2:51	SW 6020A	JTC
Conventional Chemistry Parameters								
*Reactive Cyanide	U	1.07	mg/Kg	1	8/25/09 0:00	8/25/09 0:00	SW 9014	RMN
*Ignitability (Flash Point)	>195	50.0	°F	1	8/25/09 0:00	8/25/09 0:00	SW 1010 (M)	AJD
*Paint Filter	Pass		P/F	1	8/25/09 0:00	8/25/09 0:00	SW 9095A	AJD
*pH	7.10	0.0100	pH Units	1	8/26/09 9:45	8/26/09 13:00	SW 9045C	ARR
*Reactive Sulfide	U	9.30	mg/Kg	1	8/27/09 0:00	8/27/09 0:00	SW 9034	AJD
Percent Solids	87.5	0,0100	%	1	8/25/09 13:10	8/26/09 9:45	ASTM D2216	RMN

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

TCLP Volatile Organic Compounds by GC-MS - Quality Control

Aπalyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Augryc	Nesui:	Linn	Units	Level	Result	MINER	Lining	KLD	LIEST	NOICS
Batch S002305 - SW 5030B VOA ZHE										·
Blank (S002305-BLK1)				Prepared &	: Analyzed:	08/27/2009)			
Benzene	U	0.0250	mg/L							
2-Butanone	U	0.0250	mg/L							
Carbon tetrachloride	U	0.0250	mg/L							
Chlorobenzene	U	0.0250	mg/L							
Chloroform	U	0.0250	mg/L							
4,4-Dichlorobenzene	U	0.0250	mg/L							
1,2-Dichloroethane	Ŭ	0.0250	mg/L							
,I-Dichloroethene	U	0.0250	mg/L							
Cetrachloroethene	U	0.0250	mg/L							
Trichloroethene	U	0.0250	mg/L							
Vinyl chloride	U	0.0200	mg/L							
surrogate: 4-Bromofluorobenzene	0.0526	nere autoria e en la respectación de entre e en entre entre en entre entre entre entre entre entre entre entre	mg/L	0.050000		105	67-133			
Surrogate: 1,2-Dichlorvethone-d4	0.0499		mgA	0.050000		100	86-125			
iurrogate: Toluene-d8	0.0484		mg/L	0.050000		97	81-116			
LCS (\$002305-BS1)				Prepared &	Analyzed:	08/27/2009)			
Benzenc	0.0510	0.0250	mg/L	0.050000		102	70-130			
2-Butanone	0.0845	0.0250	mg/L	0.10000		84	70-130			
Carbon tetrachloride	0.0524	0.0250	mg/L	0.050000		105	70-130			
Chlorobenzene	0.0462	0.0250	mg/L	0.050000		92	70-130			
Chloroform	0.0497	0.0250	mg/L	0.050000		99	70-130			
,4-Dichlorobenzene	0.0445	0.0250	mg/L	0.050000		89	70-130			
,2-Dichloroethane	0.0444	0.0250	mg/L	0.050000		89	70-130			
1,1-Dichloroethene	0.0420	0.0250	mg/L	0.050000		84	70-130			
Tetrachioroethene	0.0468	0.0250	mg/L	0.050000		94	70-130			
Crichloroethene	0.0438	0.0250	mg/L	0.050000		88	70-130			
Vinyl chloride	0.0468	0.0200	mg/L	0.050000		94	70-130			
Surrogate: 4-Bromofluorobenzene	0.0516		mg/L	0.050000		103	67-133			
Surrogate: 1,2-Dichloroethane-d4	0.0473		mg/L	0.050000		95	86-125			
Surrogate: Tolnene-d8	0.0474		mg/L	0.050000		95	81-116			

Page 4 of 13

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

TCLP Volatile Organic Compounds by GC-MS - Quality Control

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch S002305 - SW 5030B VOA ZHE								·		
LCS Dup (S002305-BSD1)				Prepared &	Analyzed:	08/27/2009	9			
Benzene	0.0500	0.0250	mg/L	0.050000		100	70-130	2	20	
2-Butanone	0.0846	0.0250	mg/L	0.10000		85	70-130	0.2	20	
Carbon tetrachloride	0.0518	0.0250	mg/L	0.050000		104	70-130	1	20	
Chlorobenzene	0.0454	0,0250	mg/L	0,050000		91	70-130	2	20	
Chloroform	0.0486	0.0250	mg/L	0.050000		97	70-130	2	20	
1,4-Dichlorobenzene	0.0446	0.0250	mg/L	0.050000		89	70-130	0,3	20	
1,2-Dichloroethane	0.0440	0.0250	mg/L	0.050000		88	70-130	0.9	20	
1,1-Dichloroethene	0.0388	0.0250	mg/L	0.050000		78	70-130	8	20	
Tetrachloroethene	0.0459	0.0250	mg/L	0.050000		92	70-130	2	20	
Trichleroethene	0.0431	0.0250	mg/L	0.050000		86	70-130	2	20	
Vinyl chloride	0.0451	0.0260	mg/L	0.050000		90	70-130	4	20	
Surrogate: 4-Bromofluorobenzene	0.0505		mg/L	0.050000		101	67-133	THE PROPERTY OF THE PARTY OF TH		
Surrogate: 1,2-Dichloroethane-d4	0.0472		mg/L	0.050000		94	86-125			
Surrogate: Toluene-d8	0.0471		mg/L	0.050000		94	81-116			

Page 5 of 13

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

TCLP Semi-Volatile Organic Compounds by GC-MS - Quality Control

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch S002236 - SW 3510C SVOC TCLP										
Blank (S002236-BLK1)				Prepared: (08/24/2009	Analyzed: 6	18/25/2000		,	<u>_</u>
1,4-Dichlorobenzene	U	0,0100	mg/L	Trepared.	, C. E 1, E 00 5	i indiyabu. V	7012372007			
2,4-Dinitrotoluene	U	0.0100	mg/L							
Hexachlorobenzene	υ	0.0100	mg/L							
-lexachlorobutadiene	U	0.0100	mg/L							
dexachioroethane	U	0.0100	mg/L							
2-Methylphenol	U	0.0100	mg/L							
& 4-Methylphenol	U	0.0200	mg/L							
Vitrobenzene	U	0.0100	mg/L							
Pentachlorophenol	U	0.0500	mg/L							
Pyridine	U	0,0500	mg/L							
2,4,5-Trichlorophenol	U	0.0100	mg/L							
2,4,6-Trichlorophenol	U	0.0100	mg/L							
Surrogate: 2-Fluorobiphenyl	12.8		mg/L	20.000		64	38-149			
Surrogate: 2-Fluorophenol	12.3		mg/L	20.000		61	12-95			
Surrogate: Nitrobenzene-d5	13.8		mg/L	20.000		69	42-156			
Surrogate: Phenol-d6	8.47		mg/L	20.000		-12	15-90			
Surrogate: 4-Terphenyl-d14	18.3		mg/L	20.000		91	42-137			
Surrogate: 2,4,6-Tribromophenol	20.5		mg/L	20.000		103	20-120			
LCS (S002236-BS1)				Prepared: (08/24/2009	Analyzed:	08/25/2009			
l,4-Dichlorobenzene	0.0734	0.0100	mg/L	0.10000		73	60-140			
2,4-Dinitrotoluene	0.0868	0,0100	mg/L	0,10000		87	50-150			
Hexachlorobenzene	0.118	0.0100	mg/L	0.10000		118	60-140			
-lexachlorobutadiene	0.0702	0,0100	mg/L	0.10000		70	60-140			
Hexachioroethane	0.0798	0.0100	mg/L	0.10000		80	60-140			
2-Methylphenol	0.0796	0.0100	mg/L	0.10000		80	60-140			
8 & 4-Methylphenol	0.160	0,0200	mg/L	0,20000		80	60-140			
Vitrobenzene	0.0836	0.0100	mg/L	0.10000		84	60-140			
Pentachlorophenol	0.0923	0,0500	mg/L	0.10000		92	30-170			
Pyridine	0.0532	0.0500	mg/L	0.10000		53	25-125			
2,4,5-Trichlorophenol	0.0856	0.0100	mg/L	0.10000		86	50-150			
2,4,6-Trichlorophenol	0.0816	0.0100	mg/L	0.10000		82	50-150			
Surrogate: 2-Fluorobiphenyl	14.7		mg/L	20.000		73	38-149			
Surrogate: 2-Fluorophenol	13.0		mg/L	20.000		65	12-95			
Surrogate: Nitrohenzene-d5	15.6		mg/L	20.000		78	42-156			
Surrogate: Phenol-d6	9.18		mg/I.	20.000		46	15-90			
Surrogate: 4-Terphenyl-d14	20.5		mg/L	20.000		103	42-137			
Surrogate: 2,4,6-Tribromophenol	22.8		mg/L	20,000		114	20-120			

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

Polychlorinated Biphenyls by GC-ECD - Quality Control

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch S002250 - SW 3550B PCB										
Blank (S002250-BLK1)	•••••••••••••••••••••••••••••••••••••••			Prepared: 0	08/24/2009	Analyzed: (08/25/2009			
Aroclor 1016	U	0.0330	mg/Kg wet							
Aroclor 1221	U	0.0330	mg/Kg wet							
Aroclor 1232	U	0.0330	mg/Kg wet							
Aroclor 1242	U	0.0330	mg/Kg wel							
Aroclor 1248	ប	0.0330	mg/Kg wct							
Aroctor 1254	U	0.0330	mg/Kg wet							
Aroclor 1260	U	0.0330	mg/Kg wet							
Surrogate: Decachlorobiphenyl	0.467		mg/L	0.40000	1777	117	60-140			
Surrogate: Tetrachloro-m-xylene	0.369		mg/L	0.40000		92	60-140			
LCS (S002250-BS1)				Prepared: (08/24/2009	Analyzed:	08/25/2009			
Aroclor 1016	0.713	0.0330	mg/Kg wet	0.66667		107	60-130			
Aroclor 1260	0.700	0.0330	mg/Kg wet	0.66667		105	70-130			
Surrogate: Decachlorobiphenyl	0.470		mg/L	0.40000		118	60-140			
Surrogase: Tetrachloro-m-xylene	0.391		mg/L	0.40000		98	60-140			

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

TCLP Metals by ICP-MS - Quality Control

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch S002287 - SW 3005A Metals			·							
Blank (S002287-BLK1)				Prepared &	Analyzed:	08/26/2009)			
Arsenic	U	0.00500	mg/L							
9anun	U	0.00500	mg/L							
Cadmium	U	0.00200	mg/L							
Chromium	U	0,00200	mg/L							
Lead	U	0.00500	mg/L							
Mercury	ប	0.000200	mg/L							
Selenium	U	0.00500	mg/L							
Silver	U	0.00500	mg/L							
LCS (S002287-BS1)				Prepared &	Analyzed:	08/26/2009)			
Arsenic	0.449	0.00500	mg/L	0.50000		90	80-120			
Barium	0.458	0.00500	mg/L	0.50000		92	80-120			
Cadmium	0.462	0,00200	mg/L	0.50000		92	80-120			
Chromium	0.483	0,00200	mg/L	0.50000		97	80-120			
Lead	0.479	0.00500	mg/L	0.50000		96	80-120			
Mercury	0.0164	0.000200	mg/L	0.020000		82	80-120			
Selenium	0.445	0.00500	mg/L	0.50000		89	80-120			
Silver	0.528	0.00500	mg/L	0.50000		106	80-120			
Matrix Spike (S002287-MS1)	Sou	rce: 09H0370-	02	Prepared: 0	8/26/2009	Analyzed: (08/27/2009			
Arsenic	0.556	0,00500	mg/L	0,50000	ND	111	75-125			
Barium	0.866	0.00500	mg/L	0.50000	0.381	97	75-125			
Cadmium	0.612	0.00200	mg/L	0,50000	0.218	79	75-125			
Chromium	0.486	0.00200	mg/L	0,50000	ND	97	75-125			
Mercury	0.0147	0,000200	mg/L	0.020000	0,000157	73	75-125			
Selenium	0.608	0,00500	nig/L	0.50000	ND	122	75-125			
Silver	0.442	0.00500	mg/L	0.50000	ND	88	75-125			

Page 8 of 13

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

TCLP Metals by ICP-MS - Quality Control

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch S002287 - SW 3005A Metals										
Matrix Spike (S002287-MS2)	Sou	rce: 09H0370	-02RE1	Prepared: (08/26/2009	Analyzed;	08/27/2009			
Lead	15.0	0.0500	mg/L	0.50000	14,3	134	75-125			
Matrix Spike Dup (S002287-MSD1)	Sou	rce: 09H0370	-02	Prepared: (08/26/2009	Analyzed:	08/27/2009			
Arsenic	0.574	0,00500	mg/L	0.50000	ND	115	75-125	3	20	
Barium	0.913	0.00500	mg/L	0,50000	0,381	106	75-125	5	20	
Cadmium	0.620	0.00200	mg/L	0,50000	0.218	80	75-125	ŧ	20	
Chromium	0.485	0.00200	mg/L	0.50000	ND	97	75-125	0.1	20	
Mercury	0.0153	0.000200	nıg/L	0.020000	0.000157	76	75-125	4	20	
Selenium	0.616	0.00500	mg/L	0,50000	ND	123	75-125	1	20	
Silver	0.376	0.00500	mg/L	0.50000	ND	75	75-125	16	20	
Matrix Spike Dup (S002287-MSD2)	Soc	rce: 09H0370	-02RE1	Prepared; 08/26/2009 Analyzed; 08/27/2009						
Lond	14.6	0.0508	теσЛ	0.50000	14 3	52	75.125	3	20	

Page 9 of 13

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

Conventional Chemistry Parameters - Quality Control

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch S002268 - ASTM D2216 Moisture										
Blank (S002268-BLK1)				Prepared: (8/25/2009	Analyzed: (08/26/2009			
Percent Solids	U	0.0100	%							
Duplicate (S002268-DUP1)	Sou	rce: 09H0442	-09	Prepared: (8/25/2009	Analyzed: (08/26/2009			
Percent Solids	82.4	0.0100	%		81.7			0,9	20	
Batch S002270 - SW Ch 7 Sec 7.3.3 Cyanid	e Rx									
Blank (S002270-BLK1)				Prepared &	: Analyzed:	08/25/2009	9			
Reactive Cyanide	υ	1.25	mg/Kg							
LCS (S002270-BS1)				Prepared &	Analyzed:	08/25/200	9			
Reactive Cyanide	1.29	1.25	mg/Kg	2.5000		52	20-120			
LCS Dup (S002270-BSD1)				Prepared &	Analyzed:	08/25/200	9			
Reactive Cyanide	1.35	1.25	mg/Kg	2.5000		54	20-120	4	20	
Matrix Spike (S002270-MS1)	Sou	rce: 09H0388	-01	Prepared &	Analyzed:	08/25/200	9			
Reactive Cyanide	0.958	1.07	mg/Kg	2.1368	ND	45	20-120			
Matrix Spike Dup (S002270-MSD1)	Sou	rce: 09H0388	-01	Prepared 8	Analyzed:	08/25/200	9			
Reactive Cyanide	1.12	1.12	mg/Kg	2.2321	ND	50	20-120	16	20	
Batch S002273 - SW 1010 Flash Point										
LCS (S002273-BS1)				Prepared &	analyzed	08/25/200	9			
Ignitability (Flash Point)	80.0	50.0	°F	78.000		103	80-120			

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

Conventional Chemistry Parameters - Quality Control

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Notes
Batch S002295 - SW 9045C pH			+					•		
Duplicate (S002295-DUP1)	Sou	rce: 09H0307	-05	Prepared &	: Analyzed:	: 08/26/200	9			
рН	9.20	0.0100	pH Units		9.20			0	15	
Batch S002344 - SW Ch 7 Sec 7.3.4 Sulfid	e Rx									
Biank (S002344-BLK1)				Prepared &	Analyzed	: 08/27/200	9			
Reactive Sulfide	U	9.50	mg/Kg							
LCS (S002344-BS1)				Prepared &	Analyzed	: 08/27/200	9			
Reactive Sulfide	253	9.50	mg/Kg	271.40		93	30-100			
LCS Dup (S002344-BSD1)				Prepared &	: Analyzed	: 08/27/200	9			
Reactive Sulfide	259	9,50	mg/Kg	271.40		95	30-100	2	20	
Matrix Spike (S002344-MS1)	Sou	rce: 09110388	-01	Prepared &	: Analyzed	: 08/27/200	19			
Reactive Sulfide	182	9.19	mg/Kg	262.48	ND	69	30-100	Printer of decimal and assess Without	-Production Astrophysical Additional Additio	11.00 - 1.00 t. 11.00 t 1 . 1.00 t. 11.00 t.
Matrix Spike Dup (S002344-MSD1)	Sou	rce: 09H0388	-01	Prepared &	: Analyzed	: 08/27/200	19			
Reactive Sulfide	214	9,46	mg/Kg	270,32	ND	79	30-100	16	20	

Page 11 of 13

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0388

Notes and Definitions


P1 Pass

* NELAC certified compound.

U Analyte not detected (i.e. less than RL or MDL).

Chain of Custody Record

The street





Client	CPI E	NVIRON	JMENIA	12 504	THES IN	C Glient P	roject :	COMETCO				
Address	1123	NHEAS	^		-	Project L	ocation	CHIC	AGO, .	IL.		
City, Slate Zip Code	WHEA	702	IL	***		Sampler(s) /	Phone No.	FRANK	L SANTE	2CH 6	30 407 0800	
Phone / Facsimile No.	400 40	770800	0 163	10 407	0779	Tumarou	nd Time		,Rush () D			
Contact Person	FRAN	IL SA	WFELL	A		P.O. # or Ir	voice To	:				
Sample Description	Sam	pling	Cont	alner	³ M/ ⁴ P	1	Analys	ls and / or Met	had Remiesta	ų	Laboratory	
(10 Charaoters Only)	Date	Time	^{1/} Size	² Type/-No.	Code		Pulalys	is and / Or Met	noe megpeak		Comments -	
COMP-1	08/19/09	1215	32 ot	G11	51A	PAINT	Ferror	DREN-	CSP FL	MSHPUIN	VT.	
				. 1	1	PH: RE	ATIVE C	VANIA	E 101	to file	AUV.	
				1	1	REACTION	IE SUL	FIDE	TCLP M	TETALS:		
				1	1	TCLP OF	GANIC	, when	CROSE		PEB	
				1	1	AND F	CORE	; beve ni	SCAA	<u> </u>		
				1	/							
				1	1						Section Services	
					. 1						66 K. 275 A.S. KALADA	
				1	1							
				I_{c}	- 1					·		
				/	1						18 7 <u>11</u> 114 115 115 115 115 115 115 115 115 115	
					1				6. 136. a v			
Size of Container	40	mL'	125	mL	250	mL	500	mL .	100	0 mL	O - Other (Specify)	
² Type of Container	G - Glas	s (Clear)	AG - Glas	s (Amber)	Pel	IDRE	VC - Vol	atile Core	SC-S	oll Core	O - Other (Speafy)	
^{:3} M ⇒ Matrix Gode	A-Ac	ueous ·	* EW-Dim	king Water	NA - Non-ad	udous Liquid	8E÷Sall	ne Water	\$ - \$	Solids	O - Other (Specify)	
⁴ P = Preservative Code	A-1	Vone	B+H	INO₁	G-H	ZSO,	D-1	laOH	٤.	HCI	O - Other (Specify)	
Religgu	ished By		Date	Time		Receiv	ed By		Dale	Time	Method of Shipment	
frank)	Maci	<u> </u>	08/19/09	1700	Xet)	EX /	W/L	/	-/-/-			
/	· . ·				/ ※		/ aw		8 20 09	9:45	tellex	
					1 10	<u>~~~</u>			<u>/ / </u>			
Special Instructions:	' 1 ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '		•								Temperalure (°C).	

Page 13 of 13



Monday, September 28, 2009

Mr. Frank Santella

CPI Environmental Services, Inc. 1123 Wheaton Oaks Court Wheaton, IL 60187

TEL: (630) 407-0800 FAX: (630) 407-0799

RE: Sims - Cometco / Chicago, IL

PAS WO:

0910393

Prairie Analytical Systems, Inc. received 1 sample(s) on 9/22/2009 for the analyses presented in the following report.

All applicable quality control procedures met method specific acceptance criteria unless otherwise noted.

This report shall not be reproduced, except in full, without the prior written consent of Prairie Analytical Systems, Inc.

If you have any questions, please feel free to contact me at (217) 753-1148.

Respectfully submitted,

Kristen A. Potter

Project Manager

Certifications:

NELAP/NELAC - IL #100323

Prairie Analytical Systems, Inc.

Date: 9/28/2009

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Sims - Cometco / Chicago, IL

Lab Order: 0910393

Client Sample ID: Collection Date:

Comp-2

9/22/09 12:05

Lab ID: 09I0393-01

Matrix: Solid

Analyses	Result	Limit	Qual	Units	DF	Date Prepared	Date Analyzed	Method	Analyst
Conventional Chemistry Parameters									
*Phenolics	U	4.24		mg/Kg	1	9/25/09 0:00	9/25/09 0:00	SW 9065 (M)	AJD

Page 2 of 5

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Sims - Cometco / Chicago, IL

Lab Order: 0910393

Conventional Chemistry Parameters - Quality Control

		Reporting		Spike	Source		%REC		RPD	
Analyte	Result	Limit	Units	Level	Result	%REC	Limits	RPD	Limit	Nates
Batch S002836 - SW 9065 Phenols Modified	·									
Blank (S002836-BLK1)				Prepared &	: Analyzed:	09/25/200	9			
Phenolics	U	5.00	mg/Kg							
LCS (S002836-BS1)				Prepared &	Analyzed	09/25/200	9			
Phenolics	23.3	5.00	mg/Kg	25.000		93	80-120			
Matrix Spike (S002836-MS1)	Sou	rce: 09I0393-	01	Prepared &	: Analyzed:	09/25/200	9			
Phenolics	22.9	4,59	mg/Kg	22.936	ND	100	80-120			
Matrix Spike Dup (S002836-MSD1)	Sou	rce: 0910393-	01	Prepared &	: Analyzed	: 09/25/200	9			
Phenolics	19.8	4.07	mg/Kg	20 325	ND	98	80-120	14	15	

Page 3 of 5

Prairie Analytical Systems, Inc.

Date: 9/28/2009

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Sims - Cometco / Chicago, IL

Lab Order: 0910393

Notes and Definitions

NELAC certified compound.

U Analyte not detected (i.e. less than RL or MDL).

Central IL- 1210 Capital Airport Drive - Springfletd, IL 62707-8490 - Phone (217) 753-1148 - Facsimile (217) 753-1152 Chicago Office - PO Box 2116 - Crystal Lake, IL 60039-2116 - Phone (847) 651-2604 - Facsimile (847) 458-9680

www.prairieanalytical.com



				.,											Syste	MS, INCORPORATED
Client	CPI						X ⁴	A service		Analysis	and/or n	nethod R	equestec			Reporting
Äddress	1123 WHE	ATON O	ALD	CI			g.									TACO
City, State Zip Code	WHEATON	, IL	6018-	7			reste	7							ŧ	Resid
Phone / Facsimile No.	630-407 -	-0800	. 16	30-4	07-0	2999	Requested	70								Ind/Comn
Client Project	SIMS - CO						method	PHEWOLD								CALM
Location	CHICAGO						met	포				5				A B
Sampler(s) / Phone	897-384-		/ f	DAUJO (CAUTC	KUHAN	Z jo									c
Turneround Time	Standard Rust		quired:		,	,	Sis si	OTP/								RISC
P.O. # or Invoice To	FRANK SAI	UTELLA	CH 100 DO 101				Analysis	岸								Resid
Contact Person	h	*					٩	7								Indust
Sample Description	Sampl Date	ing Time	Matrix Code ¹	Total # of Containers		nple Grab										Laboratory Comments
OMP-Z	09/22/09	1205	3		بخر			><	*		-					

							- 1 (1) (1) (1) (1) (1) (1) (1) (1) (1) (
,							i Le est									
*																
							1041 T									
							1.55									
							i wa ma									
¹ M = Matrix Code	A - Aqueous		- Drinking	-		- Groundw	ater			us Liquid		S - Solids				r (Specify)
Relinqui	shed By	manage and the contraction	ale	, i k , Tu	300 (000 000)			Receiv	ed By	94.9860		D:	ate	367,965,967,00	ne .	Method of Shipmen
		99/12	2109	1530	<u>)</u>	\longrightarrow	7	X	2	Ţ,		1-2	407	153	5 <u>0</u>	1,00
		<u> </u>	4-04	173	<u>ر</u>		$\not \perp$	<u> </u>	[K)			9/2	3/119	11'1	<u> 20</u>	UPS
	<u> </u>			<u> </u>		L/	_)		7 "			1	./		Second Surface	<u> </u>
pecial Instructions:									Q/C Lev		On Wet/		Y		Ten	iverature (°¢)
								1 2	3_	_ 4	Properio	eservation	٧٠٠٠	// N	- Lung	

Page 5 of 5

Page of

Copies: White - Client Yellow - PAS, Inc. Pink - Sampler

		PCB	REMEDIAL ACTION CO	OMPLETION REPORT ment Midwest, Inc.
		150	09 West Cortland Stree	et, Chicago, Illinois
A a di 4 . C	Ionovator Wasta	Duofilo West	to Manifost and	Cools Tisket
Appendix 4. G	Generator Waste	Prome, wasi	e mannest and	Scale Ticket

Generator's Nonhazardous Waste Profile Shee

107026IL

	Requested Disposal Facility Countryside	RD	F	Profile	Number	, = ,
WASTE MANAGEMENT	🔾 Renewal for Profile Number		Wa:	ste Approval Expira	ation Date <u>09</u>	-01-10 8H
A. Waste Gene	rator Facility Information (mu:	t re	dect locat	lon of waste g	eneration/ori	gin)
1. Generator Name:	Metal Management Midwest, Inc.					
2. Site Address: <u>15</u>	09 Cortland Street		7. Email Add	lress: <u>debble.hays</u>	@simsmm.com	
3. City/ZIP: Chicag	o / 60642		8. Phone: <u>7</u>	73-846-2121	9. FAX: <u>77</u>	3-646-5010
4. State: Illinois			10. NAICS Co	de: <u>421930</u>		
5. County: <u>Cook</u>						
6. Contact Name/Ti	tle: Deborah Hays / SHEC Director		12. State ID#	(if applicable): 0	316005505	
B. Customer I	nformation C same as above		P. O. Number:			
1. Customer Name:	CPI Environmental Services, Inc.	6.	Phone: 630-	407-0800	FAX: 630-40	7-0799
	1123 Whealon Oaks Court					
	P: Wheaton, Illinois 60187					
	rank Sanlella					
	antel@continentalplacer.com					
	m Information					
1. DESCRIPTION						
	Name: Contaminated Soll				·	
State Waste Co						
b. Describe Proce	ss Generating Waste or Source of Contami	natio	on:			
Remedial Act	ion Activities					
c. Typical Color(s)						
	☐ Yes ☑ No Describe: Slight petrole:					
	it 70°F: 🗹 Solid 🖸 Liquid 🔘 Po		r 🔾 Semi-So	olid or Sludge 🛚 🗖	Other:	
	Single layer 🔲 Multi-layer 🗹 NA					
	Yes 🗹 No If Yes, Describe:					
	ge (%): to Of NA(
	1 <2					
j. Liquid Flash Poi		u	NA(solid)	ઉ Actual: <u>>195</u>		ļ
k. Flammable Solid	: ures us no rents: List all constituents of waste stream	n - 6	e a Sail 0-809	6. Wood 0-20%)*	D (See Attache	a)
Constituents (Total Camposi			Lower Range	Unit of Measure	Upper Range	init of Heasure
1. Soil	k, Cinders, Gravel, and wood		90	Percent	95	Percent
3.	a, Cindars, Graver, and wood	١	3	Parcent	i5	Percent
4		i_			,	
5 6.						i
	Y OF WASTE AND SHIPPING INFORMATION					1
	☐ Base ☐ Repeat Event			m	C) 600	
	I Quantity: 15 O Tons O C					Į.
	cy: Units per					Q Other
	partment of Transportation (USDOT) Hazan			•		
• • •	Description (if applicable): N/A					
SAPPLY REUDIREMEN	IS (Handling, PPE, etc.): N/A					/



Generator's Nonhazardous Waste Profile Sheet

107026 IL

D. Regulatory Status (Please check appropriate	responses)		
1. Is this a USEPA (40 CFR Part 261)/State hazardous waste? If yes, con	ntact your sales representative.	☐ Yes	€ No
2. Is this waste included in one or more of categories below (Check all		☐ Yes	S) No
☐ Delisted Hazardous Waste ☐ Exc	luded Wastes Under 40 CFR 261.4		
☐ Treated Hazardous Waste Debris ☐ Trea	ated Characteristic Hazardous Waste		
3. Is the waste from a Federal (40 CFR 300, Appendix B) or state manda	ated clean-up? If yes, see instructions.	Yes	Ø No
4. Does the waste represented by this waste profile sheet contain radio	active material?	O Yes	™ No
a. If yes, is disposal regulated by the Nuclear Regulatory Commission			
b. If yes, is disposal regulated by a State Agency for radioactive wast	•		
5. Does the waste represented by this waste profile sheet contain conce		Ø Yes	□ No
a. If yes, is disposal regulated under TSCA?	SO Yes CJ No	~	mK
6. Does the waste contain untreated, regulated, medical or infectious w		Yes	MO No
7. Does the waste contain asbestos?	If Yes, Q Friable		
8. Is this profile for remediation waste from a facility that is a maj	or source of Hazardous Air Pollutants (Site Remediation	,	•
40 CFR 63 subpart GGGGG)?	☐ Yes	Ø No	
If yes, does the waste contain <500 ppmw VOHAPs at the p	oint of determination?	☐ No	
E. Generator Certification (Please read and certif	y by signature below)		
By signing this Generator's Waste Profile Sheet, I hereby certify that all:			
1. Information submitted in this profile and all attached documents con	tain true and accurate descriptions of the waste material;		
2. Relevant information within the possession of the Generator regarding	known or suspected hazards pertaining to this waste has	been	
disclosed to WM/the Contractor;	- -		İ
3. Analytical data attached pertaining to the profiled waste was derived	from testing a representative sample in accordance with		
40 CFR 261.20(c) or equivalent rules; and	-		
4. Changes that occur in the character of the waste (i.e. changes in the	process or new analytical) will be identified by the Generato	or .	ĺ
and disclosed to WM (and the Contractor if applicable) prior to provid	·		
5. Check all that apply:			1
☐ Attached analytical pertains to the waste, Identify laboratory & sa	mple ID #'s and parameters tested:		
	# Pages	:	
Only the analyses identified on the attachment pertain to the wast	te (identify by laboratory & sample ID #'s and parameters to	ested).	- 1
Attachment #: Leboratory Report - Prairie Analytical Systems, is	nc. dated September 22, 2009		[
 Additional information necessary to characterize the profiled waste 	has been attached (other than analytical).		1
Indicate the number of attached pages:			1
I am an agent signing on behalf of the Generator, and the delegation	on of authority to me from the Generator for this signature	is	- 1
available upon request.			-
By Generator process knowledge, the following waste is not a listed	waste and is below all TCLP regulatory limits.		
Certification Signature: 1714 Many	Title: Safety Health Environmental & Community Direct	Ò.	
· · · · · · · · · · · · · · · · · · ·		<u> </u>	
Company Name: Metal Management Midwest, Inc.	Name (Print): Deborah Hays		
Date:		····	
	use only		
Management Method: 🔀 Landfill 🗆 Bioremediation	Approval Dacision: Approved O Not App	roved	
□ Non-hazardous solidification □ Other: 25 Codisposal	Waste Approval Expiration Date: 09-01-1		
Management Facility Precautions, Special Handling Procedures or Li	mitation O Shall not contain free liquid		
on approvals. Approved as special woster.	1. Co. O Shipment must be scheduled into dispo	sal facili	ty
on approvals per remediation waste < 50 ppm acceptab subtitle Dianafili per 40 (FR 761.61 (A)(1) 15 day notification submitted 09/21/09. Firs shipment can occur an or after 10/09/09.	5)(v)(A). Il Annoval Number must accome and	thiomen	ř
15 day notification submitted 09/21/04, Eirs	The second and the second and sec	ampine)	.
an process can secur an or atter 10/04/04	Waste Manifest must accompany load		1
VM Authorization Name / Title:	Coth culton Date: 69-29	-09	-
tate Authorization (If Required):	Date:		_
, , , , , , , , , , , , , , , , , , , ,			

Ple	ase print or t			n ente (12-pltch) type	awriter.)						Form.	Approved. I	OMB No. :	2050-0039
		HAZARDOUS 1	I. Çenerator ™	7 Number 0316005505		2. Page 1 of	3. Emergen	cy Respons	e Phone	1	Trecking Nur	L 69% 4		JK
	5, Gene cati	CHACLE MER DO	CLOCK		1	· ·	Generator's	Sile Meter s	Vidriegovina	nrivideatri	Mt.			
	127	101 S Daty Ave	nue					1509 C	Cortland Str	eet	1	(+	3	
Ш	Chi	cago, IL 60633	3	Attn: Deborah	Hays/ SHEC Direc	tor		Chicag	io, IL 6064	2			1	
	Generalore	Dane.		563-340-7208		1		·		()	11.		φ	
										Ú S. EFA ID	Nichter			-
	SE	er 1 Company Name I Environimenta	<u>ŧ</u> ĺ		Special Waste ID	# UPW-23	32773-IL			1	10 11001			
Π	7 Transports	er 2 Company Name	,, <u></u> ,		847-537-9221			······································		U.S. EPA IO I	U:MA			
	T. Caliagona	er z wanipar y man e								1	ininge:			
П	A #0.7	al Facility (see as as as as	*11-1-4							1				
	ŧ	inystor care								U.S. EPA ID 1	rauper			
		25 North Route												
	Gra	iyslakė, IL 6000		ı	IL ID #090702500	103								
	Facility's Pho	1941 194:	-223-2722	<u>'</u>										
				oper Shipping Name, H	azard Cleas, iD Number,		L	10. Conta	iners	17 10/8	12 Unit	13 1/2	Vasie Code	ь
Ш	HM and	Packing Group (if any	YÌ)					Na.	Туре	Quantity	Wt Mat.	13. 7	18815 CODE:	,
	1.								- /					
P	Not	Hazerdous by	DOI COM	aminated soil				1	CM	/ <u>('Y')</u>	↓ } ⊢			
2			_					1		7 25	/	1		
GENERATOR	Ž.		- 1		٢				V	/				
15		11		ムムレフ	(ı			-				
П	1		- 1)) / _	\mathcal{O}									
11.	1								1		†	TO COLUMN TO STATE OF THE PARTY	****	······································
		-			11 -	コト								×_
	<u> </u>				l	$M \cap \mathcal{A}$						1		
	4.					<u> </u>								
		,									L			
	_												1	ı
	44. Special r	landing instructions.	and Addisons	Information					<u> </u>		<u></u>			
1	Prof	file#1070261L)	\									JCK # 💪	1/4
N.	100	d 1	ad 2	Losed 3	Load 4				-			i n.	TCK #	1,00
Ш														
	15. GENER	ATOR STOPP EROR	S CERTIFICA	TION: Thereby declar	e that the contents of this	consignment a	re fully and a	ccuretely de	escribed above	by the proper sh	ipping name,	and are class	sified, packa	ged,
					ondition for transport acco the terms of the anached				konal governme	ntel regulations.	fexport ship	ment and i a	in the Prima	iry
\prod					r viersettis ut the atlachet ₹ 262.27(a) (if lem a large				all quantity gen	ersion) s true.				
$\ \cdot\ $	Generator s/C	Offeror's PrintegiType	id Name			Sign	state)		11		`	Mont	h Day	Year
↓	1 R id	cardo	تمد	ime		<u> </u>	1000	Mok	`)	1/5	مل ا د	109
1	15. Internation			η το U.S		Expart from U		Port of en	Jan Luite					
Ē	Transporter s	shooke ref) erusanple		I, IÇ D.3	<u> </u>	Ехран нол ч	.S.	Date leavi					· · · · · · · · · · · · · · · · · · ·	
<u> </u>	17. Transporté	er Acknowledgment o	Receipt of M	alerials					<u></u>				····	*******
E	Transporter	Primad/Typed Name	}		A	Siçn	alure C					Month	Day	Year
S.	رنجم هڪ	Para Dis	A Argum			1						1/	کے ای	901
22	Transporter 2	Printed/Typed Name)			Sign	alure	/				Mont		Year
TRANSPORTER						1							.	
 	18. Discrepan	ecv.				L	·							
IT		ncy Indication Space									DOM:		7	
Ш	i Qa. Diausapa	mey manuanch aphico	, [_] O	uantity	Type		Re	esidue		Pertie! Reju	ittion	<u> </u>	Full Relati	otien
>-	198 Abarnosa	Facility (or General)	-/-				Marries	I Reference	Number:	U.S. EPA ID N	nonhar			
5	TOO. PRISE PRISE	7 John J. Denesan	"]							ea.compn	Nil Arti			
유										ł				
Ö	Facility's Phon	re. cof Alternate Facility	(ar Concealor							<u> </u>		Mone	th Day	Year
	TOC. DIGITIONS	O Anerosce - Busty	(ci ceseina)) e- '								1410111	ii Deiy	1
DESIGNATED FACILITY							Opportunities and the second							
Ē	19 Hazardous	: Wasle Réport Mare	igement Meth	·	niseri elaaw audonasari ro	rent, disposal,	end recycling	systems)				4.		
ᅙ	<i>i.</i>	~		2.	•	. X		_		4.				
	4	{		1		/_/	_A_	-/1						
	4). Des grister		peyator: Centif	isation of receipt of haz	erdous malenals covered	ty is mand	elexagola≗r	coop in light	18a	· , -,,			- Pi	
	19 7°	Name	-	C\		N. Sign	7 0				ł	, Mon	100	70
L٠		<u> </u>	M				\sim		$\nu \nu u$			<u> </u>	lor	$U\downarrow$
FFA	Form: 8700-2	12 (Rev. 3-05), Pre-	vious edition	is are dosolete.		' n	COMMAND.	TOD EA	AR DEV TO	Treetin	ATIANI Ĉ	TATE /	בסבתו	HOERN

Out-Bound Transfe	r						Oct 08, 2009
Ticket # TKUFY1 ID: BLUE Vehicle # TK TKUFY1	Transfer	TICKET		Date Ship Date		/08/09 /08/09	Ticket Info
Transfer to: MTLM2F MTLM - CALIFORNIA 3151 S CALIFORNIA AVE CHICAGO, IL 60608							Add Item
Itm Shpmnt Material	- G	ross		Pounds Net		Pd Wt	Edit Item
1. TKUFY1 MIXED LOADS		4440b	35720a	28720 28720		28720 28720	icket Comment
Gross Wight Date/Time Tare Wight Date/Time					ROSS T 12.8	214	View Photos
				4	28	120 105.	Place In-Yard
					21,	620 LBS. 620 Pt.	icket Complete
					a and a second		More >

PO.MW030644

WEIGHMASTER CERTIFICATE TRUCK SCALE

*** WEIGHT DNLY TICKET ***

Ticket #: WKACY5



METAL MANAGEMENT MIDWEST, INC.

Phone: 773-254-1200

SHIP DATE: 08/19/09

Sold To: CPOZDP PCB BOX

MTLM - CORTLAND 1509 W. CORTLAND ST. CHICAGO, IL 60622

Veh # TK WKACY5 ID	# SET	Order #	1060 Lm 01	Mat Req#	1060COM in 01		
SHPMNT# COMMODITY		GROSS TARE	NET A	JJ REASON	rugices at enter at the later and later at the later at later	ADJ NET WT	Charlette wheeling
439535 USABLE SCRAP		32940m 25840b	day the day in the state of the same	0	वरः इतिक्रोदिक की दिख्य के प्रशासन्त्रभावाचा इतिकासीय करा अन्	7100	province property in the province of the provi
ALL WEIGHTS A	RE REPORTED IN	POUNDS UNLESS	OTHERWISE	INDICATED. A	LL NON-POUND WEIG	HTS ARE ASSUMED TO BE	MANUAL WEIGHTS
							4.7
TICKET COMMENT: DROPP	ING OFF PCB BC	i den sterrikke presi X					+
						GRS Date 08/19/09	GROSS TONS
WEIGHMASTER SIGN		In-in W A				GRS Time 09:03	3.1696
CUSTOMER SIGNATI		laria M.)				TRE Date 08/19/09 TRE Time 09:03	1
=SCALE 1 b=SCALE 2	c=SCALE 3	d=SCALE 4	m=MANU/	AL WEIGHT		*************	+
understand it is unlawful to re- emoved before appliances or r			-			to the atmosphere and that a	ny CFC's must be proper
		previously lea					
L	(2) all CFC's	were properly	recovered	l in accordar	nce with 40 C.F.F	R. Section 82.156(g)	and (h) by:
ro entiendo que es contra la le emovidos appropiadementa a							C's tienen que estar
					ados de este cont		
	• •		recuperad	os en forma	appropiada de a	cuerdo con 40 C.F.F	R. Section 82,156
	(g) y (h) por	lame/Nombre:				·	
		ess/Direccion:					
		Date/Fecha:					
C: 1/C:_							
Signed/Fir Printed No	r <u>ma:</u> ame:/Nombre:						 .
		cion del vende	edor:			2.10	
		es/Motor Vehic		ditioners rec	overed		
Tipo y # A	partos/Airess	acondicionado	os de carro	s Recupera	do		
		·	•				WW
Date/Fech	12	MANAGER COLUMN TO CO			- 12-	**************************************	**************************************
101011 CO	r						

Appendix 5. Laboratory Analytical Report for Excavation Confirmatory Samples



Thursday, August 27, 2009

Mr. Frank Santella CPI Environmental Services, Inc. 1123 Wheaton Oaks Court Wheaton, IL 60187

TEL: (630) 407-0800 FAX: (630) 407-0799

RE: Cometco / Chicago, IL

PAS WO:

09H0387

Prairie Analytical Systems, Inc. received 12 sample(s) on 8/20/2009 for the analyses presented in the following report.

All applicable quality control procedures met method specific acceptance criteria unless otherwise noted.

This report shall not be reproduced, except in full, without the prior written consent of Prairie Analytical Systems, Inc.

If you have any questions, please feel free to contact me at (217) 753-1148.

Respectfully submitted,

Kristen A. Potter

Project Manager

Certifications:

NELAP/NELAC - # 100323

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Client Sample ID:

Collection Date:

Cometco / Chicago, IL

TP-302B

8/19/09 10:20

Lab Order: 09H0387

Lab 1D: 09H0387-05

Matrix: Solid

Analyses	Result	Limit	Qual	Units	DF	Date Prepared	Date Analyzed	Method	Analyst
Polychlorinated Biphenyls by GC-ECD									
*Arocior 1016	U	0.0406		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:20	SW 8082	CJM
*Aroclor 1221	U	0.0406		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:20	SW 8082	CJM
*Aroclor 1232	U	0.0406		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:20	SW 8082	CJM
*Aroclor 1242	U	0.0406		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:20	SW 8082	CJM
*Aroclor 1248	U	0,0406		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:20	SW 8082	СЛМ
*Aroclor 1254	U	0,0406		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:20	SW 8082	CJM
*Aroclor 1260	U	0.0406		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:20	SW 8082	СТМ
Surrogate: Decachlorohiphenyl		112%		60-14	0	8/24/09 16:22	8/25/09 15:20	SW 8082	CJM
Surrogate: Tetrachloro-m-xylene		90 %		60-14	0	8/24/09 16:22	8/25/09 15:20	SW 8082	СЈМ
Conventional Chemistry Parameters									
Percent Solids	80.9	0.0100		%	1	8/25/09 13:10	8/26/09 9:45	ASTM D2216	RMN

Page 2 of 9

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0387

Client Sample ID: Collection Date:

TP-302 Comp 8/19/09 10:35 Lab ID: 09H0387-06

Matrix: Solid

Analyses	Result	Limit	Qual	Units	DF	Date Prepared	Date Analyzed	Method	Analyst
Polychlorinated Biphenyls by GC-ECD									
*Aroclor 1016	U	0.0380		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:54	SW 8082	CJM
*Aroclor [22]	υ	0.0380		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:54	SW 8082	CJM
*Aroclor 1232	ប	0.0380		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:54	SW 8082	CIM
*Aroclor 1242	U	0.0380		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:54	SW 8082	СЛМ
*Aroclor 1248	U	0.0380		mg/Kg dry	ì	8/24/09 16:22	8/25/09 15:54	SW 8082	CJM
*Aroclor 1254	U	0.0380		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:54	SW 8082	CJM
*Aroclor 1260	0.299	0.0380		mg/Kg dry	1	8/24/09 16:22	8/25/09 15:54	SW 8082	CJM
Surrogate: Devachlorohiphenyl		96 %		60-14	10	8/24/09 16:22	8/25/09 15:54	SW 8082	СЈМ
Surrogate: Tetrachloro-m-xylene		86 %		60-14	0	8/24/09 16:22	8/25/09 15:54	SW 8082	CJM
Conventional Chemistry Parameters									
Percent Solids	85.6	0.0100		%	1	8/25/09 13:10	8/26/09 9:45	ASTM D2216	RMN

Page 3 of 9

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, 1L

Lab Order: 09H0387

Client Sample 1D:

TP-310B

Lab ID: 09H0387-10

Collection Date:

8/19/09 11:50

Matrix: Solid

Analyses	Result	Limit	Qual	Units	DF	Date Prepared	Date Analyzed	Method	Analyst
Polychlorinated Biphenyls by GC-ECD									•
*Aroclor 1016	U	0.0457		mg/Kg dry	1	8/24/09 16:22	8/25/09 16:27	SW 8082	CJM
*Aroclor 1221	U	0.0457		mg/Kg dry	1	8/24/09 16:22	8/25/09 16:27	SW 8082	СЈМ
*Aroclor 1232	U	0.0457		mg/Kg dry	1	8/24/09 16:22	8/25/09 16:27	SW 8082	CJM
*Aroclor 1242	U	0.0457		mg/Kg dry	1	8/24/09 16:22	8/25/09 16:27	SW 8082	CJM
*Aroclor 1248	U	0.0457		mg/Kg dry	1	8/24/09 16:22	8/25/09 16:27	SW 8082	CJM
*Aroclor 1254	U	0.0457		mg/Kg dry	l	8/24/09 16:22	8/25/09 16:27	SW 8082	CJM
*Aroclor 1260	U	0.0457		mg/Kg dry	1	8/24/09 16:22	8/25/09 16:27	SW 8082	СЈМ
Surrogate: Decachlorobiphenyl		110%		60-14	9	8/24/09 16:22	8/25/09 16:27	SW 8082	CJM
Surrogate: Tetrachloro-m-xylene		94 %		60-140)	8/24/09 16:22	8/25/09 16:27	SW 8082	СЈМ
Conventional Chemistry Parameters									
Percent Solids	72.2	0 0100		%	1	8/25/09 13:10	8/26/09 9:45	ASTM D2216	RMN

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0387

Client Sample ID:

Lab ID: 09H0387-11

Collection Date:

TP-310 Comp 8/19/09 12:13

Matrix: Solid

Analyses	Result	Limit	Qual	Units	DF	Date Prepared	Date Analyzed	Method	Analyst
Polychlorinated Biphenyls by GC-ECD									
*Araclor 1016	U	0.0382		mg/Kg dry	1	8/24/09 16:22	8/25/09 17:01	SW 8082	CJM
*Aroclor 1221	U	0.0382		mg/Kg dry	1	8/24/09 16:22	8/25/09 17:01	SW 8082	CJM
*Aroclor 1232	U	0.0382		mg/Kg dry	1	8/24/09 16:22	8/25/09 17:01	SW 8082	CJM
*Aroclor 1242	U	0.0382		mg/Kg dry	I	8/24/09 16:22	8/25/09 17:01	SW 8082	CJM
*Aroclor 1248	U	0.0382		mg/Kg dry	1	8/24/09 16:22	8/25/09 17:01	SW 8082	СЈМ
*Aroclor 1254	U	0.0382		mg/Kg dry	1	8/24/09 16;22	8/25/09 17:01	SW 8082	CJM
*Aroclor 1260	0.564	0.0382		mg/Kg dry	1	8/24/09 16:22	8/25/09 17:01	SW 8082	СЈМ
Surrogate: Decachlorohiphenyl		82 %		60-14	0	8/24/09 16:22	8/25/09 17:01	SW 8082	CJM
Surrogate: Tetrachloro-m-xylene		81 %		60-14	0	8/24/09 16:22	8/25/09 17:01	SW 8082	CJM
Conventional Chemistry Parameters									
Percent Solids	85.9	0.0100		%	1	8/25/09 13:10	8/26/09 9:45	ASTM D2216	RMN

Page 5 of 9

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0387

Polychlorinated Biphenyls by GC-ECD - Quality Control

Amalista	Demili	Reporting	1 haita	Spike	Source	N/BEG	%REC	nnn	RPD	Notes
Analyte	Result	Limit	Units	l_evel	Result	%REC	Limits	RPD	Limit	Notes
Batch S002250 - SW 3550B PCB										
Blank (S002250-BLK1)				Prepared: (08/24/2009	Analyzed: (08/25/2009			
Aroctor 1016	U	0.0330	mg/Kg wet							
Aroclor 1221	U	0.0330	mg/Kg wet							
Aroclor 1232	Ü	0 0330	mg/Kg wet							
Aroclor 1242	U	0,0330	mg/Kg wet							
Aroclor 1248	U	0.0330	mg/Kg wet							
Arcelor 1254	U	0.0330	mg/Kg wct							
Aroctor 1260	U	0.0330	mg/Kg wet							
Surrogate: Decachtarohiphenyl	0.467		mg/L	0.40000		117	60-140			
Surragate: Tetrachloro-m-xylene	0.369		mg/L	0.40000		92	60-140			
LCS (S002250-BS1)				Prepared: (08/24/2009	Analyzed: (08/25/2009			
Aroclor 1016	0.713	0.0330	mg/Kg wet	0.66667		107	60-130			
Aroclor 1260	0.700	0.0330	mg/Kg wet	0,66667		105	70-130			
Surrogate: Decachlorobiphenyl	0.470		mg/l.	0.40000		118	60-140			
Surrogate: Tetrachloro-m-xylene	0.391		mg L	0.40000		98	60-140			

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

82,4

Project:

Percent Solids

Cometco / Chicago, IL

Lab Order: 09H0387

0.9

20

Conventional Chemistry Parameters - Quality Control

Analyte	Result	Reporting Limit	Units	Spike Level	Source Result	%REC	%REC Limits	RPD	RPD Limit	Notes
Batch S002268 - ASTM D2216 Moisture										
Blank (S002268-BLK1)				Prepared: (08/25/2009	Analyzed:	08/26/2009			
Percent Solids	U	0.0100	%							
Dunficate (S002268-DUP1)	Source: 09H0442-09			Prepared: (08/25/2009	Analyzed:	08/26/2009			

%

81.7

0,0100

Page 7 of 9

LABORATORY RESULTS

Client:

CPI Environmental Services, Inc.

Project:

Cometco / Chicago, IL

Lab Order: 09H0387

Notes and Definitions

NELAC certified compound.

U Analyte not detected (i.e. less than RL or MDL).

Chain of Custody Record

1210 Capital Airport Drive • Springlield, IL 62707-8490 • Phone (217) 753-1148 • Facsimile (217) 753-1152 • E-mall into@prairieanalytical.com



Client	CPI E	ENVERON	MENTA	L SERVI	RES INC	Client Project	COMETCO				
Address	1123 V	NHEATO	N OKK	S CT.		Project Location	CHICAGO, IL				
City, State Zip Code	WHEATON, IL 60187					Sampler(s) / Phone No.	FRANK SANTELA 1 630 407 0800				
Phone / Facsimile No.	630 407 0800 1630 407 0799					Turnaround Time	Standard K Rush [] Date Required:				
Gontact Person	FRANK SANTELLA					P.O. # or Invoice To					
Sample Description	Sampling Container ³ M / ⁴ P					Analy	sis and / or Method Requested		Laboratory		
(10 Characters Only)	Date	Time	¹ Size	² Type/No.	Code	riie.j		Comments			
TP-302N	08/17/09	1025	402	GII	SIA		- <u></u>				
TP-302S	ζ	1030		(/)	('1		110/1		6946.07628683806386		
TP-3026		1031		11	1 / \		<u> </u>				
TP-302W		1035		11							
TP-302B	/	1020			11/1	PCB5			\$1.00 mg/ (\$1) sale asin		
TP-302 COMP		1035			1	PCBS					
TP-310N		1155		1					The state of the s		
TP-3105		1205		11/1			- HOLD	<u> </u>			
TP-310E	:	1200			1 /		1,000				
TP-310W	. /	1210		11/							
TP-310B		1150				PCBs					
TP-310 COMP	Ψ	12/3	7	4 14	1 14	PCBs					
¹ Size of Container	40	mL	128	5.mL"	250) mL 50	0 mL 1000	mL	O - Other (Specify)		
² Type of Container	G - Glas	s (Clear)	AG - Glas	ss (Amber)	P-H	IDPE VC-Vo	latile Core SC - So	l Core	O - Other (Specify)		
3 M = Matrix Code	. A≃Ad	jueous 🖰 💮	DW Drin	king Water	NA - Non-ac	lnaona Fidulq SE • Sa	Slids	O - Other (Specify)			
⁴ P = Preservative Code	A-1	None	B-1	HNO ₃	C-H	1250 ₄ D+	NaOH E⊸F	+CI	O - Other (Specify)		
Relingu	shed By		Date	Time		Received By	Date Date	Time	Method of Shipment		
france.	James	wa	03/19/09	1700	PL	WEX) H					
/	-		· · · · ·			- HA	1 8/20/09	9:45	FedEX		
					1 19		//				
Special Instructions:									Temperature (°C)		

Page 9 of

Ø